

OS image for 8028GX8-AC Release Notes

Version: v1.4.1

Release Date: 2021-09-01

• Applicable Products

8028GX8-AC

New Features

N/A

Enhancements

- Bugs Fixed
 - 1. Fix memory leakage that every 15 mins will increase 4k memory even if ptp is disabled
 - 2. Fix "Date and Time Settings" page will cause zombie 'sh'



Release Date: 2021-07-01

• Applicable Products

8028GX8-AC

New Features

N/A

• Enhancements

N/A

• Bugs Fixed



Release Date: 2021-3-23

• Applicable Products

8028GX8-AC

New Features

1. LLDP supported system name.

• Enhancements

N/A

• Bugs Fixed



Release Date: 2021-03-17

• Applicable Products

8028GX8-AC

New Features

N/A

• Enhancements

- Bugs Fixed
 - 1. Fix ERPS recovery time issue



Release Date: 2020-12-21

• Applicable Products

8028GX8-AC

New Features

1. Use new MIB.

• Enhancements

N/A

• Bugs Fixed



Release Date: 2020-12-01

• Applicable Products

8028GX8-AC

New Features

N/A

Enhancements

- Bugs Fixed
 - 1. Fix the vulnerability that when the DHCP server and DHCP listening are enabled at the same time, the device may report an error, which can not manage the Web, telnet and console, but can ping the switch



Release Date: 2020-11-26

• Applicable Products

8028GX8-AC

New Features

N/A

• Enhancements

- Bugs Fixed
 - 1. Fix web storm control can not disable.



Release Date: 2020-10-29

• Applicable Products

8028GX8-AC

New Features

N/A

Enhancements

- Bugs Fixed
 - 1. Fix some multicast packets, such as 224.0.0.251224.0.252 and IPV6 multicast packets, which will cause ERPS switching/recovery failure
 - 2. Fix that when igmp snooping is disabled, the window MDNS packet will forward two MDNS packets



Release Date: 2020-10-22

• Applicable Products

8028GX8-AC

• New Features

N/A

• Enhancements

1. Improve the system boot time to about 1 min 30 sec.

• Bugs Fixed



Release Date: 2020-10-20

• Applicable Products

8028GX8-AC

New Features

N/A

• Enhancements

N/A

• Bugs Fixed



Release Date: 2020-09-29

• Applicable Products

8028GX8-AC

New Features

N/A

• Enhancements

- Bugs Fixed
 - 1. Fix WEB storm control can not disable



Release Date: 2020-09-24

• Applicable Products

8028GX8-AC

- New Features
 - 1. VLAB and MAC function enabled the SAL-DPC abstraction layer to avoid lock issue
- Enhancements

N/A

• Bugs Fixed



Release Date: 2020-09-24

• Applicable Products

8028GX8-AC

New Features

N/A

Enhancements

- Bugs Fixed
 - 1. Fix the loss of the original configuration after downtime
 - 2. Fix when enable igmp snooping and igmp query, sending igmp packets will cause the machine to report an error and restart automatically



Release Date: 2020-09-15

• Applicable Products

8028GX8-AC

- New Features
 - 1. Apply thread to rx handler to avoid lock issue
- Enhancements

- Bugs Fixed
 - 1. Fix the DHCP packet is treaded as broadcast packet when forwarding to other port