



OS image for 8028GX8-L3 Release Notes

Version: **v1.4.1**

Release Date: **2021-09-01**

- **Applicable Products**

8028GX8-L3

- **New Features**

N/A

- **Enhancements**

N/A

- **Bugs Fixed**

1. Fix memory leakage that every 15 mins will increase 4k memory even if ptp is disabled
2. Fix "Date and Time Settings" page will cause zombie 'sh'

Version: **v1.4**

Release Date: **2021-07-01**

- **Applicable Products**

8028GX8-L3

- **New Features**

N/A

- **Enhancements**

N/A

- **Bugs Fixed**

N/A

Version: **v1.3.3**

Release Date: **2021-3-23**

- **Applicable Products**

8028GX8-L3

- **New Features**

1. LLDP supported system name.

- **Enhancements**

N/A

- **Bugs Fixed**

N/A

Version: **v1.3.2**

Release Date: **2021-03-17**

- **Applicable Products**

8028GX8-L3

- **New Features**

N/A

- **Enhancements**

N/A

- **Bugs Fixed**

1. Fix ERPS recovery time issue

Version: **v1.3.1**

Release Date: **2020-12-21**

- **Applicable Products**

8028GX8-L3

- **New Features**

1. Use new MIB.

- **Enhancements**

N/A

- **Bugs Fixed**

N/A

Version: **v1.3**

Release Date: **2020-12-01**

- **Applicable Products**

8028GX8-L3

- **New Features**

N/A

- **Enhancements**

N/A

- **Bugs Fixed**

1. Fix the vulnerability that when the DHCP server and DHCP listening are enabled at the same time, the device may report an error, which can not manage the Web, telnet and console, but can ping the switch



Version: **v1.2.18**

Release Date: **2020-11-26**

- **Applicable Products**

8028GX8-L3

- **New Features**

N/A

- **Enhancements**

N/A

- **Bugs Fixed**

1. Fix web storm control can not disable.

Version: **v1.2.17**

Release Date: **2020-10-29**

- **Applicable Products**

8028GX8-L3

- **New Features**

N/A

- **Enhancements**

N/A

- **Bugs Fixed**

1. Fix some multicast packets, such as 224.0.0.251 and 224.0.0.252 and IPV6 multicast packets, which will cause ERPS switching/recovery failure
2. Fix that when igmp snooping is disabled, the window MDNS packet will forward two MDNS packets

Version: **v1.2.16**

Release Date: **2020-10-22**

- **Applicable Products**

8028GX8-L3

- **New Features**

N/A

- **Enhancements**

1. Improve the system boot time to about 1 min 30 sec.

- **Bugs Fixed**

N/A

Version: **v1.2.15**

Release Date: **2020-10-20**

- **Applicable Products**

8028GX8-L3

- **New Features**

N/A

- **Enhancements**

N/A

- **Bugs Fixed**

N/A

Version: **v1.2.13**

Release Date: **2020-09-29**

- **Applicable Products**

8028GX8-L3

- **New Features**

N/A

- **Enhancements**

N/A

- **Bugs Fixed**

1. Fix WEB storm control can not disable

Version: **v1.2.12**

Release Date: **2020-09-24**

- **Applicable Products**

8028GX8-L3

- **New Features**

1. VLAB and MAC function enabled the SAL-DPC abstraction layer to avoid lock issue

- **Enhancements**

N/A

- **Bugs Fixed**

N/A

Version: **v1.2.11**

Release Date: **2020-09-24**

- **Applicable Products**

8028GX8-L3

- **New Features**

N/A

- **Enhancements**

N/A

- **Bugs Fixed**

1. Fix the loss of the original configuration after downtime
2. Fix when enable igmp snooping and igmp query, sending igmp packets will cause the machine to report an error and restart automatically

Version: **v1.2.9**

Release Date: **2020-09-15**

- **Applicable Products**

8028GX8-L3

- **New Features**

1. Apply thread to rx handler to avoid lock issue

- **Enhancements**

N/A

- **Bugs Fixed**

1. Fix the DHCP packet is treaded as broadcast packet when forwarding to other port