

OS image for SEVR-Mx Release Notes

Version: v41.60701.1014P05

Release Date: 2022-08-18

• Applicable Products

SEVR-Mx

- New Features
 - 1. Support Chinese and English languages to follow the browser language.
 - 2. Add support for FLASH TOOL operation command.
 - 3. Support hardware watchdog.
- Enhancements
 - 1. Optimize debug printout.
- Bugs Fixed
 - 1. Solve the problem of plugging and unplugging the network cable of TCP CLIENT, disconnection and connection BUG.



Version: v41.60701.1014P04

Release Date: 2022-07-11

• Applicable Products

SEVR-Mx

• New Features

N/A

- Enhancements
 - 1. Packing time and length logic adjustment
- Bugs Fixed
 - 1. When the serial port is configured to start packing time and length, the TCP Server connection will be disconnected immediately



Version: v41.60701.1014P03

Release Date: 2022-07-05

• Applicable Products

SEVR-Mx

• New Features

N/A

• Enhancements

N/A

- Bugs Fixed
 - 1. Modify the Nebula in UDP mode, the network receives data and sends it from the serial port to all "0"



Version: v41.60701.1013

Release Date: 2022-06-10

• Applicable Products

SEVR-Mx

- New Features
 - 1. Support SSH function.
 - 2. Support reverse TELNEL.
- Enhancements
 - 1. Modify the Nebula in UDP mode, the network receives data and sends it from the serial port to all "0"
 - 2. Update the display of relevant information on the home page of the system
- Bugs Fixed
 - 1. Some bugs related to the WEB interface